

AD-A156 873 NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS  
BAKER FLOODWATER RESE. (U) CORPS OF ENGINEERS WALTHAM  
MA NEW ENGLAND DIV JUN 79

AD-A156 873 NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS  
BAKER FLOODWATER RESE. (U) CORPS OF ENGINEERS WALTHAM  
MA NEW ENGLAND DIV JUN 79

AD-A156 873 NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS  
BAKER FLOODWATER RESE. (U) CORPS OF ENGINEERS WALTHAM  
MA NEW ENGLAND DIV JUN 79

UNCLASSIFIED F/G 13/13


UNCLASSIFIED F/G 13/13

UNCLASSIFIED F/G 13/13

END

14 | Page

Journal Pre-proof



MICROCOPY RESOLUTION TEST CHART  
NATIONAL BUREAU OF STANDARDS-1963-A

AD-A156 873


MERRIMACK RIVER BASIN  
WENTWORTH, NEW HAMPSHIRE

**BAKER FLOODWATER RESERVOIR  
SITE 6A**

**NH 00477**

NHWRB NO. 249.15

**PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM**



**DEPARTMENT OF THE ARMY  
NEW ENGLAND DIVISION, CORPS OF ENGINEERS  
WALTHAM, MASS. 02154**

**DISTRIBUTION STATEMENT A**  
Approved for public release  
Distribution Unlimited

**DTIC FILE COPY**

**JUNE 1979**

**85 06 26 062**

64

## **DISCLAIMER NOTICE**

**THIS DOCUMENT IS BEST QUALITY  
PRACTICABLE. THE COPY FURNISHED  
TO DTIC CONTAINED A SIGNIFICANT  
NUMBER OF PAGES WHICH DO NOT  
REPRODUCE LEGIBLY.**

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

AD A 156 873

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER NH 00477	2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER
4. TITLE (and Subtitle) Baker Floodwater Reservoir Site 6A  NATIONAL PROGRAM FOR INSPECTION OF NON-FEDERAL DAMS		5. TYPE OF REPORT & PERIOD COVERED INSPECTION REPORT
7. AUTHOR(s) U.S. ARMY CORPS OF ENGINEERS NEW ENGLAND DIVISION		6. PERFORMING ORG. REPORT NUMBER
9. PERFORMING ORGANIZATION NAME AND ADDRESS		8. CONTRACT OR GRANT NUMBER(s)
11. CONTROLLING OFFICE NAME AND ADDRESS DEPT. OF THE ARMY, CORPS OF ENGINEERS NEW ENGLAND DIVISION, NEDED 424 TRAPELO ROAD, WALTHAM, MA. 02254		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)		12. REPORT DATE June 1979
		13. NUMBER OF PAGES 87
		15. SECURITY CLASS. (of this report)  UNCLASSIFIED
		18a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report)  APPROVAL FOR PUBLIC RELEASE: DISTRIBUTION UNLIMITED		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES Cover program reads: Phase I Inspection Report, National Dam Inspection Program; however, the official title of the program is: National Program for Inspection of Non-Federal Dams; use cover date for date of report.		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) DAMS, INSPECTION, DAM SAFETY, Merrimack River Basin Wentworth New Hampshire Tural Brook		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number)  The dam is a 730 ft. long 60 ft. high earthen structure. The visual inspection revealed that the dam is in excellent condition. The items noted in this report do not warrant a reduction in the assessed condition of the dam. It is intermediate in size with a high hazard potential. There are various remedial measures which should be implemented by the owner.		



DEPARTMENT OF THE ARMY  
NEW ENGLAND DIVISION, CORPS OF ENGINEERS  
424 TRAPELO ROAD  
WALTHAM, MASSACHUSETTS 02154

REPLY TO  
ATTENTION OF:  
NEDED

SEP 29 1979

Honorable Hugh J. Gallen  
Governor of the State of New Hampshire  
State House  
Concord, New Hampshire 03301

Dear Governor Gallen:

Inclosed is a copy of the Baker Floodwater Reservoir, Site-6A Phase I Inspection Report, which was prepared under the National Program for Inspection of Non-Federal Dams. This report is presented for your use and is based upon a visual inspection, a review of the past performance and a brief hydrological study of the dam. A brief assessment is included at the beginning of the report. I have approved the report and support the findings and recommendations described in Section 7 and ask that you keep me informed of the actions taken to implement them. This follow-up action is a vitally important part of this program.

A copy of this report has been forwarded to the Water Resources Board, the cooperating agency for the State of New Hampshire. In addition, a copy of the report has also been furnished the owner, New Hampshire Water Resources Board, Concord, New Hampshire 03301.

Copies of this report will be made available to the public, upon request, by this office under the Freedom of Information Act. In the case of this report the release date will be thirty days from the date of this letter.

I wish to take this opportunity to thank you and the Water Resources Board for your cooperation in carrying out this program.

Sincerely,

MAX B. SCHEIDER  
Colonel, Corps of Engineers  
Division Engineer

Incl  
As stated

BAKER FLOODWATER RESERVOIR SITE 6A

NH 00477

NHWRB 249.15

MERRIMACK RIVER BASIN  
WENTWORTH, NEW HAMPSHIRE

Accession For	
NTIS GRA&I	<input checked="" type="checkbox"/>
DTIC TAB	<input type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification	
By	
Distribution/	
Availability Codes	
Dist	Avail and/or Special
A/	

PHASE I INSPECTION REPORT  
NATIONAL DAM INSPECTION PROGRAM



NATIONAL DAM INSPECTION PROGRAM  
PHASE I - INSPECTION REPORT  
BRIEF ASSESSMENT

Identification No.: 00477  
Name of Dam: Baker Floodwater Reservoir Site 6A  
Town: Wentworth  
County and State: Grafton, New Hampshire  
Stream: Tural Brook  
Date of Inspection: May 17, 1979

Baker Floodwater Reservoir Site 6A is a 730 foot long 60 foot high earthen structure. There are two different fill zones in the dam including a cut off wall. Top width of the dam is 20 feet. The upstream and downstream embankments are on a 3 horizontal to 1 vertical slope. Appurtenant structures consist of a principal spillway, plunge pool stilling basin, emergency spillway, and a 24 inch gated pond drain pipe. The principal spillway has two inlets, a low stage orifice and a high stage covered top spillway. The inlets discharge through the riser to a 3.0 foot diameter concrete pipe. The dam construction was completed in November 1975. Plans, design calculations and construction data were prepared by the Soil Conservation Service and are available for inspection.

The visual inspection revealed that the dam is in excellent condition. The items noted in this report do not warrant a reduction in the assessed condition of the dam. The visual inspection revealed staining of the concrete on the riser structure, log debris along the reservoir banks and a fallen tree in the channel downstream of the dam.


Based on the intermediate size of the dam and its high hazard classification and in accordance with Corps of Engineers guidelines, the test flood inflow is equal to the Probable Maximum Flood (PMF) or 8000 cfs. The routed test flood outflow of 5760 cfs overtops the dam by 1.2 feet. With the water level at the top of dam, the spillways will pass 33 percent of the routed test flood outflow. As there is a high hazard to loss of life from large flows downstream of the dam, a review using  $\frac{1}{2}$  the PMF was made. The analysis indicates that the  $\frac{1}{2}$  PMF inflow would be 4000 cfs. As the maximum capacity of the spillway is 1900 cfs the dam will



not be overtopped. Hydraulic design calculations indicate that the principal spillway was designed to retard flows for up to a 100 year frequency flood. The crest elevation of the dam was designed using a total watershed runoff of 6.81 inches.

There are no recommendations resulting from the Phase I Inspection. Remedial measures include development of a downstream warning system in the event of emergency conditions, the removal of log debris from the reservoir banks, and the removal of a fallen tree in the downstream channel.

The remedial measures are described in Section 7 and, unless otherwise noted, should be addressed within two years after receipt of this Phase I Inspection Report by the owner.





*Gordon H. Slaney, Jr.*


Gordon H. Slaney, Jr., P.E.  
Project Engineer

Howard, Needles, Tammen & Bergendoff  
Boston, Massachusetts


This Phase I Inspection Report on Baker Floodwater Reservoir Site 6A has been reviewed by the undersigned Review Board members. In our opinion, the reported findings, conclusions, and recommendations are consistent with the Recommended Guidelines for Safety Inspection of Dams, and with good engineering judgment and practice, and is hereby submitted for approval.

  
JOSEPH W. FINEGAN, JR., MEMBER  
Water Control Branch  
Engineering Division

  
CARNEY M. TERZIAN, MEMBER  
Design Branch  
Engineering Division

  
JOSEPH A. MCELROY, CHAIRMAN  
Chief, NED Materials Testing Lab.  
Foundations & Materials Branch  
Engineering Division

APPROVAL RECOMMENDED:

  
JOE B. FRYAR  
Chief, Engineering Division

## PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I Investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D.C. 20314. The purpose of a Phase I Investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation and analyses involving topographic mapping, subsurface investigations, testing and detailed computational evaluations are beyond the scope of a Phase I Investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action, while improving the stability and safety of the dam, removes the normal load on the structure and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that unsafe conditions be detected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established Guidelines, the Spillway Test Flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. Because of the magnitude and rarity of such a storm event, a finding that a spillway will not pass the test flood should not be interpreted as necessarily posing a highly inadequate condition. The test flood provides a measure of relative spillway capacity and serves as an aide in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition and the downstream damage potential.

## TABLE OF CONTENTS

<u>Section</u>	<u>Page</u>
Letter of Transmittal	
Brief Assessment	
Review Board Page	
Preface	i
Table of Contents	ii-iv
Overview Photo	v
Location Map	vi

## REPORT

1. PROJECT INFORMATION	1-1
1.1 General	1-1
a. Authority	1-1
b. Purpose of Inspection	1-1
1.2 Description of Project	1-1
a. Location	1-1
b. Description of Dam and Appurtenances	1-2
c. Size Classification	1-2
d. Hazard Classification	1-2
e. Ownership	1-2
f. Operator	1-2
g. Purpose of Dam	1-3
h. Design and Construction History	1-3
i. Normal Operational Procedure	1-3
1.3 Pertinent Data	1-3
2. ENGINEERING DATA	2-1
2.1 Design Data	2-1
2.2 Construction Data	2-1
2.3 Operation Data	2-1
2.4 Evaluation of Data	2-1

<u>Section</u>	<u>Page</u>
3. VISUAL INSPECTION	3-1
3.1 Findings	3-1
a. General	3-1
b. Dam	3-1
c. Appurtenant Structures	3-2
d. Reservoir Area	3-3
e. Downstream Channel	3-3
3.2 Evaluation	3-3
4. OPERATIONAL PROCEDURES	4-1
4.1 Procedures	4-1
4.2 Maintenance of Dam	4-1
4.3 Maintenance of Operating Facilities	4-1
4.4 Description of any Warning System in Effect	4-1
4.5 Evaluation	4-1
5. HYDRAULIC/HYDROLOGY	5-1
5.1 Evaluation of Features	5-1
a. General	5-1
b. Design	5-1
c. Experience Data	5-1
d. Visual Observation	5-1
e. Overtopping Potential	5-1
f. Dam Failure Analysis	5-2
6. STRUCTURAL STABILITY	6-1
6.1 Evaluation of Structural Stability	6-1
a. Visual Observation	6-1
b. Design and Construction Data	6-1
c. Operating Records	6-1
d. Post-Construction Changes	6-1
e. Seismic Stability	6-1

<u>Section</u>	<u>Page</u>
7. ASSESSMENT, RECOMMENDATIONS AND REMEDIAL MEASURES	7-1
7.1 Dam Assessment	7-1
a. Condition	7-1
b. Adequacy of Information	7-1
c. Urgency	7-1
d. Need for Additional Investigation	7-1
7.2 Recommendations	7-1
7.3 Remedial Measures	7-1
7.4 Alternatives	7-1

#### APPENDIXES

APPENDIX A - INSPECTION CHECKLIST

APPENDIX B - ENGINEERING DATA

APPENDIX C - PHOTOGRAPHS

APPENDIX D - HYDROLOGIC AND HYDRAULIC COMPUTATIONS

APPENDIX E - INFORMATION AS CONTAINED IN THE NATIONAL  
INVENTORY OF DAMS

SECTION 5  
HYDROLOGY AND HYDRAULIC ANALYSIS

5.1 Evaluation of Features

a. General. Baker Dam Site 6A is an earthen embankment dam 730 feet long with a hydraulic height of 60 feet. The dam is constructed with two fill zones and an earth fill core which extends to bedrock over a portion of the length of the dam. Appurtenant works consist of a two stage riser and a 3 foot diameter concrete pipe which discharges to a plunge pool type stilling basin, an emergency spillway 80 feet wide and a 24 inch diameter gated pond drain pipe.

The dam is used for floodwater control and recreation. The dam is classified as intermediate in size having a height of 60 feet and maximum storage of 1209 acre-feet.

b. Design Data. According to the Soil Conservation Service design data this dam is constructed to retard flood flows of up to a 100 year frequency storm without utilizing the emergency spillway. The design flood control elevation is 970.3 feet or 0.2 feet below the emergency spillway crest. Total runoff for this condition is 3.30 inches during a six hour Type IIB storm. The crest of the dam was designed using a total watershed runoff of 6.81 inches. The structure is classified as having a "B" hazard, which is defined as "being located in a predominantly rural or agricultural area, where failure may cause damage to isolated homes, main highways or major railroads or cause interruption of use or service or relatively important utilities.

c. Experience Data. There are no records available of maximum discharge at the dam site. However during the inspection of the dam on May 17, 1979 it was noted that debris on the face of the dam reached to about elevation 967.0 which would correspond to a discharge of about 220 cfs.

d. Visual Observations. No evidence of damage to any portion of the project from overtopping was visible at the time of inspection.

e. Test Flood Analysis. Even though detailed design and operational data are available for this dam a hydrologic evaluation was performed using a test flood equal to the Probable Maximum Flood (PMF) as determined from Guide Curves issued by the Corps of Engineers. Based on a drainage area of 3.35 square miles, it was estimated that the test flood inflow at Baker Dam Site 6A would be 8000 cfs. Following

## SECTION 4 OPERATIONAL PROCEDURES

### 4.1 Procedure

Baker Dam Site 6A is used for floodwater control and recreation. Under normal operating procedures the dam is left to function as designed. The recreation pool level is maintained by the low stage orifice opening in the riser. Flood events of up to a 100 year frequency are retarded by the reservoir storage between the recreation pool and the emergency spillway crest. The emergency spillway is utilized only with events greater than a 100 year frequency.

### 4.2 Maintenance of Dam

The dam is inspected on an annual basis by the New Hampshire Water Resources Board and the Soil Conservation Service. Maintenance is undertaken as a result of the inspection on an as needed basis. The dam is visited on a monthly basis by personnel of the Water Resources Board.

### 4.3 Maintenance of Operating Facilities

Maintenance of the outlet works is performed as in Section 4.2.

### 4.4 Description of Warning Systems

There are no warning systems in effect for this facility.

### 4.5 Evaluation

The current operation and maintenance procedure for this facility appear to be adequate to insure that any problems encountered can be remedied within a reasonable period of time. However, the owner should establish a downstream warning system to follow in the event of emergency conditions.



The pond drain structure consists of an inlet structure and a 24 inch diameter reinforced concrete pipe. The 24 inch pond pipe is extended to the riser structure and is controlled by a mechanically operated gate. The pond drain structure and control gate were under water at the time of inspection. The gate and control mechanism are housed in the concrete riser tower. The operating mechanism appeared to be in good condition.

The outlet works conduit consists of 36 inch diameter reinforced concrete pipe and is placed on a concrete bedding. The pipe and the bedding are in good condition as shown in Photos No. 12 & 13.

Visual inspection of outlet works discharge channel and plunge pool stilling basin showed it to be in excellent condition.

The discharge channel shown in Photo No. 12 is unobstructed to the limits of the project. The rip-rap along the channel is in excellent condition.

d. Reservoir Area. The reservoir is surrounded by wooded terrain. The left bank of the pool is grass covered. There are no cottages or dwellings along the shoreline. Log debris was noted on the right bank and a small portion of the left bank of the reservoir. Some log debris was on the face of the dam.

e. Downstream Channel. For a distance of about 200 feet downstream of the dam the channel is lined with rip-rap with grassed banks. The channel enters a wooded area with trees on both banks. There is a fallen tree across the channel located just into the wood line.

### 3.2 Evaluation

Visual examination indicates the dam is in excellent condition. Visual examination revealed the following:

- (a) Staining of concrete on the riser structure
- (b) Log debris along the reservoir banks
- (c) A fallen tree across the downstream channel

### Crest

The crest of the dam is 20 feet wide and has an excellent grass cover, as shown in Photo No. 2.

No misalignment of the crest was observed.

### Downstream Slope

The downstream slope is 2.5 horizontal to 1 vertical and has an excellent grass cover, as shown in Photo No. 7. The contact between the downstream slope and the abutments has been paved with riprap to prevent erosion. This riprap is in excellent condition.

No seepage or damp areas were observed on the downstream slope or below the toe of the dam.

The dam has a trench drain near the downstream toe which is piped to the outlet stilling basin. A small amount of water was flowing from the 12 inch diameter drainpipe exiting on the left side of the outlet pipe. The foundation drainpipes are shown in Photo No. 13.

c. Appurtenant Structures. Visual inspection of the concrete riser principal spillway structure, auxiliary earth spillway and outlet works structure did not reveal any evidence of stability problems. The concrete surface and vertical alignment of the riser structure are in good condition except for minor rust staining. The spillway trash rack and service ladder are also in good condition. Some rust was noted around the manhole cover plate.

The concrete riser principal structure consists of three elements, an overflow control (low and high stages of spillway), a vertical transition and closed concrete discharge conduit. The riser structure is placed in the earth embankment. Visual inspection revealed that the riser structure appeared to be in good sound condition, Photos No. 9, 10 & 11.

The galvanized trash racks at the low and high stages of flow control consist of standard shape angles and grating. Both trash rack assemblies are in good condition, no rust or peeling of the protective coating was noted.

The emergency earth spillway, Photos No. 15, 16 & 17 is a grassy channel reinforced with riprap or rock, and is located in left abutment. The emergency spillway leads to the downstream channel of Tural Brook. The downstream channel has steep embankments on both sides. The channel is heavily wooded. The emergency spillway is in excellent condition.

## SECTION 3 VISUAL INSPECTION

### 3.1 Findings

a. General. The field inspection of Baker Dam Site 6A was made on May 17, 1979. The inspection team consisted of personnel from Howard, Needles, Tammen & Bergendoff and Geotechnical Engineers, Inc. A representative of the New Hampshire Water Resources Board was also present during the inspection. Inspection checklists, completed during the inspection, are included in Appendix A. At the time of inspection the water level was approximately 1.0 foot above the invert of the low stage inlet. The upstream face of the dam could only be inspected above this water level.

b. Dam. Visual inspection of the dam indicated that it is in excellent condition.

The dam is an earth embankment about 730 feet long and 60 feet high. The embankment consists of two zones, a wide upstream zone of silty sand and gravel and a downstream shell of sandy gravel. A cutoff trench extends below the center of the dam into bedrock or on impervious silty till. A drainage trench extends below the downstream shell at the base and the abutments of the dam.

An unpaved emergency spillway is cut into the left abutment passing around the embankment. An outlet works consisting of a concrete riser, 36-inch diameter concrete pipe passing through the dam, and a rip-rap lined stilling basin is located approximately on the center of the dam.

#### Upstream Slope

The upstream slope is 3 horizontal to 1 vertical and has a 9-foot wide berm at about mid-height. The crest elevation is 975.1 feet and between elevations 964.7 and 949.1, the slope is covered with riprap.

At the time of inspection, the pool was at about elevation 955, allowing the upper 10 feet of riprap to be inspected. The condition of the riprap is excellent. Photos No. 1 & 6 show the riprap.

The embankment slope above the riprap to the crest of the dam has an excellent grass cover, as shown in Photo No. 5.

## SECTION 2 ENGINEERING DATA

### 2.1 Design

A complete set of design data including layout, hydraulic design, foundation and embankment design, geology and soils reports, structural design, quantities and specifications are available for Baker Dam Site 6A. In addition, there are construction drawings available. Design of the dam was done by the Soil Conservation Service, Durham, New Hampshire.

### 2.2 Construction

The dam construction was completed in November of 1975. A complete record of construction documents were made available. These documents include: as-built plans, job diaries, surveying records, test drilling logs, compaction test results, concrete tests and certificate of completion. Construction was by Robie Construction Co., Inc. and was inspected by the Soil Conservation Service, Durham, New Hampshire.

### 2.3 Operation

Normally the pond drain line gate is closed. The recreational level of 954 is maintained by the low stage orifice openings. The principal spillway riser and reservoir storage is designed to retard runoff from up to a 100 year frequency storm without discharge occurring in the emergency spillway (crest 971.0).

### 2.4 Evaluation

a. Availability. Engineering data available for Baker Dam Site 6A consists of the information outlined in Sections 2.1 and 2.2. The plans, design data, and construction records are available at the offices of the Soil Conservation Service, Federal Building, Durham, New Hampshire, 03824.

b. Adequacy. A complete set of design and construction data did allow for a definitive review within the confines of this Phase I - Inspection Report. Therefore, the adequacy of this dam is based on the design and construction data reviewed, visual inspection, past performance history and sound engineering judgement.

c. Validity. The field inspection indicated that the external features of Baker Dam Site 6A substantially agree with those shown on the available plans.

### Emergency Spillway

- (1) Type - earth
- (2) Length of weir - 80 feet wide
- (3) Crest Elevation - 971.0
- (4) Gates - none
- (5) U/S Channel - Approach channel from reservoir is  
80 feet wide with  $2\frac{1}{2}$  to 1 side slopes
- (6) Downstream Channel - Below the outlet structure  
for a distance of 200 feet the channel has grass lined banks,  
and a rip-rapped channel. Downstream of this section the  
channel enters a wooded area.

j. Regulating Outlets. The recreation level of the reservoir is controlled by a 27 inch by 20 inch orifice inlet set in the riser at invert elevation 954.1. There is a trash rack for the opening but no control gate. The 24 inch pond drain pipe set at invert 917.0 extends 126 feet into the reservoir from the riser, and has a trash rack at the intake. The pipe is controlled at the riser by a 24 inch gate/valve.

f. Reservoir Surface (acres)

- (1) Recreation Pool - 28
- (2) Flood Control Pool - 50.7
- (3) Spillway Crest - 51.5
- (4) Test Flood Pool - 56.8
- (5) Top Dam - 56.8

g. Dam

- (1) Type - earth
- (2) Length - 730 feet
- (3) Height - 60 feet hydraulic  
65 feet structural
- (4) Top Width - 20 feet
- (5) Side Slopes - upstream 3 horizontal to 1 vertical,  
downstream 2½:1
- (6) Zoning - 2 fill zones
- (7) Impervious core - none
- (8) Cutoff - zone 1 fill
- (9) Grout Curtain - none
- (10) Other - none

h. Diversion and Regulating Tunnel

See Section j

i. Principal Spillway

- (1) Type - concrete riser, covered top - 3 foot diameter  
discharge discharge pipe through dam.
- (2) Length of weir - total 18 feet
- (3) Crest Elevation - 964.7
- (4) Gates - none
- (5) U/S Channel - none

(2) There are no records available of maximum discharge at the site. However, during the inspection of the dam on May 17, 1979 it was noted that debris on the face of the dam reached to about elevation 967.0 which would correspond to a discharge of about 220 cfs.

(3) The emergency spillway and riser capacity with the water surface at the top of the dam is approximately 1900 cfs at elevation 975.1.

(4) Emergency spillway and riser capacity with the water surface elevation at the test flood elevation of 976.3 is approximately 2790 cfs.

(5) The total project discharge at the test flood elevation of 976.3 is 5760 cfs.

c. Elevation (feet above MSL)

- (1) Streambed at centerline of dam - 915.
- (2) Maximum tailwater - unknown
- (3) Upstream portal invert pond drain - 917.0
- (4) Recreation pool - 954.1
- (5) Full flood control pool - 970.79
- (6) Spillway crest (riser crest) - 964.7  
(emergency spillway) - 971.0
- (7) Design surcharge - 970.79
- (8) Top Dam - 975.1
- (9) Test Flood Surcharge - 976.3

d. Reservoir (miles)

- (1) Length of Maximum Pool - .94
- (2) Length of Recreational Pool - .60
- (3) Length of Flood Control Pool - .38

e. Storage (gross acre-feet)

- (1) Recreation Pool - 326
- (2) Flood Control Pool - 960
- (3) Spillway Crest Pool - 981
- (4) Top of Dam - 1209

g. Purpose of Dam. This dam is used for both flood-water control and recreation. The recreational pool is maintained by the low stage intake in the riser. The storage between the low stage outlet and the emergency spillway crest is used for floodwater control.

h. Design and Construction History. The construction of this dam was completed in November of 1975. Design and construction inspection of this dam were done by the Soil Conservation Service, Durham, New Hampshire. The construction contractor was Robie Construction Company, Inc.

i. Normal Operating Procedures. The recreational pool is maintained by the low stage inlet on the riser. Under flood conditions, when the capacity of the low stage orifice is exceeded, the storage is utilized. The high stage outlet will reach maximum design discharge before the reservoir reaches the crest of the emergency spillway. The dam does not require any manual operation in order to function.

### 1.3 Pertinent Data

a. Drainage Area. The area tributary to Baker Site 6A consists of 3.35 square miles of mountainous terrain. There is no development in the watershed except for a camp ground. Maximum elevation is at about 1880 feet MSL, and reservoir full elevation is at 975 feet MSL.

The area around the reservoir is mostly wooded. There are no cottages or dwellings along the shoreline. A roadway divides the reservoir area with a 6 foot diameter culvert connecting the upper and lower areas of the reservoir.

#### b. Discharge of Dam Site

(1) Outlet works for Baker Dam Site 6A consist of an emergency spillway, a riser with a low stage orifice and a high stage covered top spillway, and a 24 inch pond drain pipe controlled by a gate. Invert of the pond drain is at 917.0 MSL. Maximum discharge of the pipe when the reservoir is at the recreational pool level of 954.1 is about 105 cfs. The low stage orifice has one opening 27 inches by 20 inches in size set at invert 954.1. Capacity of the low stage inlet when the reservoir is at the crest of the high stage inlet (964.7 ft) is 58 cfs. The high stage covered inlet crest set at elevation 964.7 has a capacity of 229 cfs when the water level is at the emergency spillway crest of 971.0. The 30 foot wide emergency spillway has a crest at elevation 971.0. When the water surface is at the top of dam (elevation 975.1) the emergency spillway will have a capacity of 1663 cfs.



b. Description of Dam and Appurtenances. Baker Site 6A Dam is an earthen embankment structure. Total length of the dam, according to existing drawings, is 730 feet. Maximum structural height is 65 feet, and the height from top of dam to the streambed is 60 feet. According to the plans there are two different fill zones in the structure, which include a cut off wall. Approximately 56 percent of the length of the cut off wall extends to bedrock. Top width of the dam is 20 feet and the embankment is on a 3 horizontal to 1 vertical slope both up and downstream.

Appurtenant structures consist of a concrete riser and pipe, principal spillway with a covered top inlet. There are two stages to the inlet structure, a low stage orifice and a high stage covered inlet. The riser discharges through a 3 foot diameter concrete pipe to a plunge pool type stilling basin. The emergency spillway is located on the left side of the dam and has a width of 80 feet. It is an excavated earthen structure with a vegetative cover. A 24 inch diameter pond drain pipe can be opened from the riser structure by a 24 inch gate valve to lower the water level behind the dam.

Figures 1 and 2, located in Appendix B, show a plan of the dam and appurtenant structures. Photographs of each structure are shown in Appendix C.

c. Size Classification. Intermediate (hydraulic height - 60 feet, storage - 1209 acre-feet) classification based on height being between 40 and 100 feet and storage being between 1000 acre-feet and 50,000 acre-feet as given in Recommended Guidelines for Safety Inspection of Dams.

d. Hazard Classification. The potential for hazard posed by this dam is classified as significant. Failure of this dam at maximum pool elevation (top of dam) would result in a flood wave about 24 feet high at the end of the reach studied, 1.4 miles downstream of the dam. One dwelling in the reach would be completely inundated and a camp ground and office building would be flooded.

e. Ownership. This dam is owned by the New Hampshire Water Resources Board, 37 Pleasant Street, Concord, New Hampshire.

f. Operator. This dam is maintained and operated by the New Hampshire Water Resources Board. Chairman of the Water Resources Board is Mr. George McGee, Sr.; Mr. Vernon Knowlton is Chief Engineer, Telephone No. 603/271-1110.

NATIONAL DAM INSPECTION PROGRAM  
PHASE I INSPECTION REPORT  
BAKER FLOODWATER RESERVOIR SITE 6A

SECTION 1  
PROJECT INFORMATION

1.1 General

a. Authority. Public Law 92-367, August 8, 1972, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a National Program of Dam Inspection throughout the United States. The New England Division of the Corps of Engineers has been assigned the responsibility of supervising the inspection of dams within the New England Region. Howard, Needles, Tammen & Bergendoff has been retained by the New England Division to inspect and report on selected dams in the State of New Hampshire Authorization and notice to proceed were issued to Howard, Needles, Tammen & Bergendoff under a letter of March 30, 1979 from John P. Chandler, Colonel, Corps of Engineers. Contract No. DACW33-79-C-0060 has been assigned by the Corps of Engineers for this work.

b. Purpose


(1) To perform technical inspection and evaluation of non-Federal dams to identify conditions which threaten the public safety and thus permit correction in a timely manner by non-Federal interests.

(2) To encourage and prepare the states to initiate quickly effective dam safety programs for non-Federal dams.

(3) To update, verify and complete the National Inventory of Dams.

1.2 Description of Project

a. Location. Baker Floodwater Reservoir Site 6A (Baker Dam Site 6A), also known as Grover C. Breck Dam, is located on Tural Brook approximately 1.6 miles upstream of the confluence of Tural Brook and the Baker River in the Town of Wentworth, New Hampshire. The dam is shown on U.S.G.S. Quadrangle Wentworth, New Hampshire with approximate coordinates N43°51'15" W71°55'36", Grafton County, New Hampshire. The location of Baker Dam Site 6A is shown on the preceding page.





the guidance for Estimating Effect of Surge Storage on Maximum Probable Discharge results in a routed test flood outflow of 5760 cfs. As the maximum capacity of the spillways at the top of dam is 1900 cfs (approximately 33 percent of the routed test flood outflow, the test flood will result in the dam being overtopped by approximately 1.2 feet. The test flood was routed starting at the recreation pool elevation. As there is a high hazard to life from large flows downstream of the dam (resulting from dam failure), and dam failure resulting from overtopping would significantly increase the hazard to loss of life downstream of the dam, a review using  $\frac{1}{2}$  the PMF was made. This analysis indicates that the test flood inflow would be 4000 cfs. As the total capacity of the spillways is 1900 cfs the dam will not be overtopped. There will be no freeboard as the spillways will be at maximum capacity.

f. Dam Failure Analysis. The impact of failure of the dam at maximum pool (top of dam) was assessed using the "Rule of Thumb" Guidance for Estimating Downstream Hazard Hydrographs issued by the Corps of Engineers. The analysis covered the reach extending from the dam to a point 1.4 miles downstream to the confluence of the Baker River and Tural Brook. Prior to breach of dam, downstream river stage would be about 5 feet with the spillway discharging at full capacity. Breach of dam with the water surface at the top of dam would result in a flood wave about 29 feet high. This stage would be reduced to about 24 feet at the end of the reach. One dwelling at the end of the reach would be totally inundated. A campground office building on high ground at about the same location would be flooded by about 4 feet of water. Several camp sites which would if occupied, be totally flooded.

SECTION 6  
STRUCTURAL STABILITY

6.1 EVALUATION OF STRUCTURAL STABILITY

a. Visual Observations. The visual inspection did not disclose any immediate stability problems.

b. Design and Construction Data. Design drawings and construction specifications exist and indicate the dam is a zoned embankment consisting of a wide upstream zone of silty sand and gravel and a downstream zone of sandy gravel. A cutoff trench extends below the central portion of the dam. The cutoff trench extends up both abutments. The upstream slope is 3 horizontal and 1 vertical and the downstream slope is 2.5 horizontal to 1 vertical.

A drainage trench is located beneath the downstream zone of the embankment.

A grass-covered emergency spillway passes around the embankment on the left abutment.

A review of the construction data available indicates that the dam and appurtenant structures were constructed according to the plans and specifications.

c. Operating Records. There are no operating records available for this facility.

d. Post-Construction Changes. There is no record of post-construction changes.

e. Seismic Stability. The dam is located in Seismic Zone 2 and in accordance with the recommended Phase I guidelines does not warrant seismic analysis.

SECTION 7  
ASSESSMENT, RECOMMENDATIONS AND REMEDIAL MEASURES

7.1 Dam Assessment

a. Condition. The visual inspection of Baker Floodwater Reservoir Site 6A indicates the dam is in excellent condition. The inspection revealed the items listed below, however, these items do not warrant reducing the assessed condition of the dam.

- (1) Staining of concrete on the riser structure.
- (2) Log debris along the reservoir banks.
- (3) A fallen tree across the channel downstream of the dam.

The hydraulic analysis reveals that the spillways cannot pass the routed test flood without overtopping the dam.

b. Adequacy of Information. A complete set of design and construction data did allow for a definitive review with the confines of this Phase I - Inspection Report. Therefore, the adequacy of this dam is based on the design and construction data reviewed, visual inspection, past performance history and sound engineering judgement.

c. Urgency. This dam is in generally excellent condition. The remedial measures described in Section 7.3 should be, unless otherwise noted, be accomplished within (2) two years. The remedial measures described in Sections 7.3a and 7.3b should be done during the seasonal maintenance performed by the owner.

d. Necessity of Additional Investigation. No additional investigation is needed to complete the Phase I inspection.

7.2 Recommendations

There are no recommendations resulting from the Phase I Inspection.

7.3 Remedial Measures

- (a) Remove the fallen tree from the downstream channel.
- (b) Remove the log debris from the reservoir banks.
- (c) Devise a downstream warning system to follow in the event of emergency conditions.

(d) Continue the periodic inspections on a biennial basis.

(e) Establish a system such that the reservoir level can be monitored during periods of intense rainfall.

#### 7.4 Alternatives

There are no practical alternatives to the remedial measures described in Section 7.3.



APPENDIX A  
INSPECTION CHECKLIST

VISUAL INSPECTION CHECK LIST  
PARTY ORGANIZATION

PROJECT SITE 6A, BAKER DAMDATE May 17, 1979TIME 2:30 PMWEATHER FairW.S. ELEV. 955.1 U.S. - D.N.S

## PARTY:

1. <u>G. Slaney</u>	<u>HNTB</u>	6. _____
2. <u>S. Mazur</u>	<u>HNTB</u>	7. _____
3. <u>D. LaGatta</u>	<u>GEI</u>	8. _____
4. <u>C. Osgood</u>	<u>GEI</u>	9. _____
5. _____		10. _____

PROJECT FEATURE	INSPECTED BY	REMARKS
1. <u>Dam</u>	<u>D. LaGatta, C. Osgood</u>	
2. <u>Spillway, Outlet Works</u>	<u>S. Mazur</u>	
3. <u>and Downstream Channel</u>	<u>G. Slaney</u>	
4. _____		
5. _____		
6. _____		
7. _____		
8. _____		
9. _____		
10. _____		

## PERIODIC INSPECTION CHECK LIST

PROJECT BAKER SITE No. 6A DAM DATE May 17, 1979  
 PROJECT FEATURE Earth Embankment NAME D. P. LaGatta  
 DISCIPLINE Geotechnical Engineer NAME C. E. Osgood

AREA EVALUATED	CONDITION
<u>DAM EMBANKMENT</u>	
Crest Elevation	975.1
Current Pool Elevation	955.1
Maximum Impoundment to Date	967.0 estimated from debris on dam
Surface Cracks	None
Pavement Condition	No pavement. Grass covered crest
Movement or Settlement of Crest	None apparent
Lateral Movement	None apparent
Vertical Alignment	No misalignment visible
Horizontal Alignment	No misalignment visible
Condition at Abutment and at Concrete Structures	Good condition
Indications of Movement of Structural Items on Slopes	No structural items on slopes
Trespassing on Slopes	No evidence of trespassing
Sloughing or Erosion of Slopes or Abutments	None observed
Rock Slope Protection - Riprap Failures	Riprap in good condition
Unusual Movement or Cracking at or near Toes	None observed
Unusual Embankment or Downstream Seepage	None
Piping or Boils	Left and right drains clear, left drain has very small flow of water.
Foundation Drainage Features	None
Toe Drains	None
Instrumentation System	None
Vegetation	Good grass cover.

# PERIODIC INSPECTION CHECK LIST

A-3

PROJECT SITE 6A, BAKER DAM

DATE May 17, 1979

PROJECT FEATURE Intake Channel/Structure

NAME D. LaGatta

DISCIPLINE Geotechnical/Structural Engineers

NAME S. Mazur

## AREA EVALUATED

## CONDITION

### OUTLET WORKS - INTAKE CHANNEL AND INTAKE STRUCTURE

#### a. Approach Channel

No approach channel

Slope Conditions

Bottom Conditions

Rock Slides or Falls

Log Boom

Debris

None

Condition of Concrete Lining

Low trash rack at riser structure  
is filled with debris.

Drains or Weep Holes

#### b. Intake Structure

Condition of Concrete

Concrete of riser structure at low  
intake opening and high stage prin-  
cipal spillway openings are in good  
condition. Bottom water release  
structure was under water.

Stop Logs and Slots

## PERIODIC INSPECTION CHECK LIST

A-4

PROJECT SITE 6A, BAKER DAM DATE May 17, 1979  
PROJECT FEATURE Control Tower NAME G. Slaney  
DISCIPLINE Structural/Hydraulic Engineers NAME S. Mazur

## AREA EVALUATED

## CONDITION

OUTLET WORKS - CONTROL TOWER

## a. Concrete and Structural

General Condition

Condition of Joints

Spalling

Visible Reinforcing

Rusting or Staining of Concrete

Any Seepage or Efflorescence

Joint Alignment

Unusual Seepage or Leaks in Gate Chamber

Cracks

Rusting or Corrosion of Steel

## b. Mechanical and Electrical

Air Vents

Float Wells

Crane Hoist

Elevator

Hydraulic System

Service Gates

Emergency Gates

Lightning Protection System

Emergency Power System

Wiring and Lighting System

Outlet works (bottom water release structure) consist of inlet structure and 24" I.D. reinforced concrete pipe extended to riser structure. Outlet works structure is controlled by mechanically operated gate. (from riser roof deck) Bottom water release structure was under water.

Mechanically operated gate and control mechanism are housed in concrete riser structure. Gate is operated from roof of riser structure. Gate and control mechanism appear to be in good operational condition.

# PERIODIC INSPECTION CHECK LIST

A-5

PROJECT	SITE 6A, BAKER DAM	DATE	May 17, 1979
PROJECT FEATURE	Spillway/Outlet Works Conduit	NAME	G. Slaney
DISCIPLINE	Structural/Hydraulic Engineers	NAME	S. Mazur

AREA EVALUATED	CONDITION
<u>OUTLET WORKS - TRANSITION AND CONDUIT</u>	
General Condition of Concrete	At the time of inspection outlet conduits were under water. These structures were built in 1974 and are in good condition.
Rust or Staining on Concrete	
Spalling	Outlet works conduit (dam section) consists of 36" I.D. reinforced concrete pipe and is placed on concrete bedding.
Erosion or Cavitation	
Cracking	
Alignment of Monoliths	
Alignment of Joints	
Numbering of Monoliths	

## PERIODIC INSPECTION CHECK LIST

A-6

PROJECT SITE 6A, BAKER DAM DATE May 17, 1979  
PROJECT FEATURE Outlet Structure/Channel NAME D. LaGatta, C. Osgood  
DISCIPLINE Structural/Hydraulic/Geotechnical NAME S. Mazur, G. Slaney  
Engineers

## AREA EVALUATED

## CONDITION

OUTLET WORKS - OUTLET STRUCTURE AND  
OUTLET CHANNEL

General Condition of Concrete

Concrete outlet works pipe and concrete support bedding are in good condition.

Rust or Staining

Water staining on lower section of concrete pipe.

Spalling

None

Erosion or Cavitation

None

Visible Reinforcing

None

Any Seepage or Efflorescence

None observed

Condition at Joints

Good

Drain Holes

None

Channel

Rock bottom and gravel

Loose Rock or Trees Overhanging  
Channel

none

Condition of Discharge Channel

good, clear

## PERIODIC INSPECTION CHECK LIST

A-7

PROJECT SITE 5A, BAKER DAM DATE May 17, 1979

PROJECT FEATURE Outlet Works - Spillway NAME D. LaGatta, C. Osgood

DISCIPLINE Structural/Hydraulic/Geotechnical NAME S. Mazur, G. Slanev

## AREA EVALUATED

## CONDITION

OUTLET WORKS - SPILLWAY WEIR, APPROACH  
AND DISCHARGE CHANNELS

## a. Approach Channel

General Condition	Good
Loose Rock Overhanging Channel	None
Trees Overhanging Channel	None
Floor of Approach Channel	Good grass cover

## b. Weir and Training Walls

General Condition of Concrete	This facility has two spillway structures; concrete riser or shaft spillway and emergency earth spillway located in left abutment. Both spillways are in good condition.	
Rust or Staining		None
Spalling		None
Any Visible Reinforcing		None
Any Seepage or Efflorescence		None
Drain Holes		

## c. Discharge Channel

General Channel Condition	Very good
Loose Rock Overhanging Channel	None
Trees Overhanging Channel	None
Floor of Channel	Grass covered
Other Obstructions	None



## PERIODIC INSPECTION CHECK LIST

A-8

PROJECT SITE 6A, BAKER DAMDATE May 17, 1979

PROJECT FEATURE \_\_\_\_\_

NAME \_\_\_\_\_

DISCIPLINE \_\_\_\_\_

NAME \_\_\_\_\_

## AREA EVALUATED

## CONDITION

OUTLET WORKS - SERVICE BRIDGE

## a. Super Structure

Bearings

Anchor Bolts

Bridge Seat

Longitudinal Members

Under Side of Deck

Secondary Bracing

Deck

Drainage System

Railings

Expansion Joints

Paint

This facility has no service bridge.

## b. Abutment &amp; Piers

General Condition of Concrete

Alignment of Abutment


Approach to Bridge

Condition of Seat &amp; Backwall

APPENDIX B

ENGINEERING DATA

1. LIST OF DESIGN, CONSTRUCTION AND MAINTENANCE  
RECORDS
2. PAST INSPECTION REPORTS
3. PLAN AND DETAILS



# LEGEND

INDICATES LOCATION WHERE PHOTO WAS TAKEN AND DIRECTION

THE INFORMATION SHOWN ON THESE DRAWINGS IS BASED ON THE ORIGINAL CONSTRUCTION PLANS AND VISUAL OBSERVATIONS MADE DURING THE FIELD INSPECTION. DIMENSIONS OR MATERIALS INDICATED ON THESE DRAWINGS WHICH WERE BELOW GRADE OR WATER DURING THE TIME OF INSPECTION WERE NOT VERIFIED.


THE ELEVATIONS SHOWN ARE 1929 MSL DATUM

WENTWORTH COUNTY, N.H.  
BROOK FLOODWATER RESERVOIR

DRAWN BY		CHECKED BY	
DATE		DATE	
NATIONAL ENGINEERING INSPECTION OF NON-FEEDBACK			
SITE NO. 6A			
BAKER FLOODWATER			
RESERVOIR WENTWORTH, N.H.			

Figure 1 of 2

20f(2)





PISEP

4

Caution Be extremely careful when using ladders. Check condition before using. Ladders are sometimes broken, loose, corroded, and or slippery.  
Use safety harness.

Ladders:  
inside and out

Condition of protective coating 1;  
Corrosion 1; Damaged parts 1; Loose    ;  
Other    .

Concrete:  
~~inside and out~~

Cracking 1; Spalling 1; Other deterioration 1;  
Excessive movement (check joint at riser and conduit)    ; Other    .

Trashracks:  
low and high stage

Condition of protective coatings 1; Corrosion 1;  
Damaged parts 1; Condition of fastenings    ;  
Need of gratings due to beaver    ; Safety condition (protruding fastenings, sharp edges, etc.)    ; Other    .

Manhole:

Condition of protective coatings 1; Corrosion 1;  
Damage 1; Lock operable 1; Other    .

Gate: 1/  
including lifting device, stem, guides, disc

Condition of protective coating    ; Corrosion    ;  
Damaged parts    ; Condition of fastenings    ;  
Stem alignment    ; Lubrication    ; Operation    ; Other    .

Safety Items:

Condition of warning signs    ; Condition of safety equipment    ; Other    .

COMMENTS 1/  
was adjusted by Podnev Hunt representatives on 6/14/78. Reduced leakage. Adjusted stop nut and wedges.

---

---

---

---

---

VEGETATION

	Dam	Emergency Spillways <sup>1/</sup>		Dike	Outlet Channel	Water way	Other ( )
Condition of stand (including need for lime and fertilizer)	—	—	—	—	—	—	—
Undesirable vegetation	—	1	1	—	—	—	—
Drainage (surface)	—	—	—	—	—	—	—
Erosion <sup>2/</sup>	—	—	—	—	—	—	—
Sedimentation	—	—	—	—	—	—	—
Condition of planting	—	—	—	—	—	—	—
Pest control	—	—	—	—	—	—	—
Fire control	—	—	—	—	—	—	—

COMMENTS Vegetation looks good. Tondressing worked well, one area on down-  
stream face of dam did not get tondressed. New planted trees and shrubs  
not evident.

EMBANKMENT, STRUCTURAL, & OTHER DRAINS

		Dam <sup>1/</sup>		Other	
		left	right	( )	( )
Depth of Flow (in inches above invert)	With any obstruction	—	—	—	—
	Without any obstruction	—	—	—	—
Turbidity of Discharge (yes, no)	With any obstruction	—	—	—	—
	Without any obstruction	—	—	—	—
Condition of Protective Coating	Outside	1	1	—	—
	Inside	1	1	—	—
Obstruction in Flow (yes, no)		no	no	—	—
Animal Guard Condition		1	1	—	—
Outlet Condition		1	1	—	—
Retarding Pool Elevation (ft. msl)	_____ or $\leq$ 1 (ft.)			above	orifice
Other	(being drawn down.)			below	

COMMENTS <sup>2/</sup> a little out of drainfill below pipe.

<sup>1/</sup> See sketch.

<sup>2/</sup> Drainage, surface, stream, channel, and livestock erosion.

EMBANKMENT AND EXCAVATED SLOPES

(Report riprap and vegetation and erosion condition under Items 4 and 5.)

	Dam	ES Dikes	Emergency Spillways <sup>1/</sup>		Other	
			left	right	( )	( )
Sliding or sloughing	<u>1</u>	<u>1</u>	<u>1</u>	—	—	—
Holes (rodent and other) (check especially at embankments)	<u>1</u>	<u>1</u>	<u>1</u>	—	—	—
Excessive settlement (embankments)	<u>1</u>	<u>1</u>	<u>1</u>	—	—	—
Cracks						
Traverse	<u>1</u>	<u>1</u>	<u>1</u>	—	—	—
Longitudinal	<u>1</u>	<u>1</u>	<u>1</u>	—	—	—
Seepage <sup>2/</sup>	<u>1</u>	<u>1</u>	<u>1</u>	—	—	—
Piping <sup>2/</sup>	<u>1</u>	<u>1</u>	<u>1</u>	—	—	—

COMMENTS \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

RIPRAP

	Displ. of Rock	Loss of Spalls	Loss of Bedding	Erosion of Found.	Break- down of Rock
Dam					
Upstream berm	<u>1</u>	<u>1</u>	<u>1</u>	<u>1</u>	<u>1</u>
Principal Spillway Outlet	—	—	—	—	—
Embankment Gutters					
left	<u>1</u>	<u>1</u>	<u>1</u>	<u>1</u>	<u>1</u>
right	<u>1</u>	<u>1</u>	<u>1</u>	<u>1</u>	<u>1</u>
Emergency Spillway					
location <u>all</u>	<u>1</u>	<u>1</u>	<u>1</u>	<u>1</u>	<u>1</u>
location _____	—	—	—	—	—
Waterways					
location at top of ES	<u>1</u>	<u>1</u>	<u>1</u>	<u>1</u>	<u>1</u>
location _____	—	—	—	—	—
Outlet Channel	—	—	—	—	—
Other _____	—	—	—	—	—

COMMENTS \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

<sup>1/</sup>Looking downstream.

<sup>2/</sup>Check especially at downstream face of embankments.



# MAINTENANCE CHECKLIST FOR PL 506 FLOOD CONTROL STRUCTURES

This maintenance checklist is a guide for determining the maintenance required for Public Law 506 flood control structures in New Hampshire. It doesn't take the place of experience and judgment and is not inclusive. Items of a difficult nature to check, such as principal spillway conduit condition, are not included. Intensive checks of these items are necessary at proper intervals. Review of As Built drawings, the design folder, structure history, and previous maintenance reports should be part of the inspection. Prompt maintenance is a vital part of safe and effective operation.

Except where otherwise indicated, completion of this form may be facilitated by ranking maintenance items on a 1 to 4 basis where

- 1 = satisfactory
- 2 = satisfactory, but check carefully at next inspection
- 3 = requires maintenance this season
- 4 = requires immediate attention.

229 15

NAME <u>W. J. Baker</u>	SITE <u>6A</u>	DATE <u>6-13 &amp; 14-78</u>
INSPECTED BY <u>W. J. Baker, David Villan (OWNER); M. J. Damsky, Nick Iantala, Ray</u>		
DRAWN BY <u>W. J. Baker, Ray Lenninger (S); 6/14-Nick Iantala, Ray Lenninger (S)</u>		

Run

Asphalt Road.	.	.	.	.	.	.	.	.	2
Site Erosion.	.	.	.	.	.	.	.	.	N/A
Traffic Conditions.	.	.	.	.	.	.	.	.	1
Water Level Control.	.	.	.	.	.	.	.	.	1
Traffic Control.	.	.	.	.	.	.	.	.	1

COMMENTS Plowed road ditch filled with sediment.

## 2. RESERVOIR

Timber stand at reservoir.	.	.	.	.	.	.	.	1
Debris and slash.	.	.	.	.	.	.	.	4
Sediment level in relation to low stage inlet	.	.	.	.	.	.	.	1

COMMENTS Road culvert plugged by beaver dam. Needs to be removed as soon as possible. Water could be unevenly distributed in the reservoir.

# IMPACT BASIN, SAF. BOX INLET, & MISCELLANEOUS CONCRETE STRUCTURES

(specify) \_\_\_\_\_

Concrete: Cracking\_\_\_; Spalling\_\_\_; Other deterioration  
inside and out \_\_\_; Excessive movement (check joints)\_\_\_;  
Waterstops\_\_\_; Joint sealant\_\_\_; Other\_\_\_.

Trashracks: Condition of protective coatings\_\_\_; Corrosion  
low and high stage \_\_\_; Damaged parts\_\_\_; Condition of fasten-  
ings\_\_\_; Need of gratings due to beaver\_\_\_;  
Safety condition (protruding fastenings, sharp  
edges, etc.)\_\_\_; Other\_\_\_.

Gates: Condition of protective coating\_\_\_; Corrosion  
including lifting \_\_\_; Damaged parts\_\_\_; Condition of fasten-  
device, stem, guides, ings\_\_\_; Stem alignment\_\_\_; Operation\_\_\_;  
disc, flap Lubrication\_\_\_; Wood decay\_\_\_; Other\_\_\_.

Structure Drainage: Report under "Embankment and Other Drains"

Structure, Railing, Condition of protective coating\_\_\_; Corrosion  
Grates, Barriers, \_\_\_; Damaged parts\_\_\_; Condition of Fasten-  
etc. ings\_\_\_; Wood decay\_\_\_; Safety condition  
(protruding fastenings, sharp edges, etc.)  
\_\_\_; Other\_\_\_.

Safety Items: Condition of warning signs\_\_\_; Condition of  
safety equipment\_\_\_; Other\_\_\_.

COMMENTS \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

## 9. CHANNEL

Stream obstructions.	.	.	.	.	.	.	.	.	.	.	1
Debris in stream.	.	.	.	.	.	.	.	.	.	.	1
Sediment bars controlled.	.	.	.	.	.	.	.	.	.	.	1
Plunge pool stability.	.	.	.	.	.	.	.	.	.	.	1
Fish habitat appurtenances	.	.	.	.	.	.	.	.	.	.	—
Riprap -- Report under "Riprap" (item 4)											

COMMENTS \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

7. RISER

Caution Be extremely careful when using ladders. Check condition before using. Ladders are sometimes broken, loose, corroded, and or slippery. Use safety harness.

Ladders:  
inside and out

Condition of protective coating\_\_\_\_;  
Corrosion\_\_\_\_; Damaged parts\_\_\_\_; Loose\_\_\_\_;  
Other\_\_\_\_.

Concrete:  
inside and out

Cracking\_\_\_\_; Spalling\_\_\_\_; Other deterioration\_\_\_\_;  
Excessive movement (check joint at riser and conduit)\_\_\_\_; Other\_\_\_\_.

Trashracks:  
low and high stage

Condition of protective coatings\_\_\_\_; Corrosion\_\_\_\_;  
Damaged parts\_\_\_\_; Condition of fastenings\_\_\_\_;  
Need of gratings due to beaver\_\_\_\_; Safety condition (protruding fastenings, sharp edges, etc.)\_\_\_\_; Other\_\_\_\_.

Manhole:

Condition of protective coatings\_\_\_\_; Corrosion\_\_\_\_;  
Damage\_\_\_\_; Lock operable\_\_\_\_; Other\_\_\_\_.

Gate:  
including lifting device, stem, guides, disc

Condition of protective coating\_\_\_\_; Corrosion\_\_\_\_;  
Damaged parts\_\_\_\_; Condition of fastenings\_\_\_\_;  
Stem alignment\_\_\_\_; Lubrication\_\_\_\_; Operation\_\_\_\_; Other\_\_\_\_.

Safety Items:

Condition of warning signs\_\_\_\_; Condition of safety equipment\_\_\_\_; Other\_\_\_\_.

COMMENTS WAB PERSONNEL WILL CHECK RISER & REPAIR -  
DEFICIENCIES LATER.

## VEGETATION

	Dam	Emergency Spillways <sup>1/</sup>		Dike	Outlet Channel	Water way	Other ( <u>CORROD</u> )
		left	right				
Condition of stand (including need for lime and fertilizer)	<u>2</u>	<u>2</u>	—	—	<u>NR</u>	—	—
Undesirable vegetation	<u>1</u>	<u>1</u>	—	—	<u>1</u>	—	<u>1</u>
Drainage (surface)	<u>NR</u>	<u>1</u>	—	—	<u>NR</u>	—	<u>1</u>
Erosion <sup>2/</sup>	<u>1</u>	<u>2</u>	—	—	<u>1</u>	—	<u>1</u>
Sedimentation	<u>1</u>	<u>1</u>	—	—	<u>1</u>	—	<u>1</u>
Condition of planting	<u>NR</u>	<u>2</u>	—	—	<u>NR</u>	—	<u>2</u>
Pest control	—	—	—	—	—	—	—
Fire control	—	—	—	—	—	—	—

COMMENTS SPILLWAY SLOPES VERY ROY. UPSTON FILL  
OF DAM VERY ROY. SHOULD 4 TREES BEING  
PLANTED

TREES ESTABLISHMENT PERIOD BEING NOV. 75

## 6. ENHANCEMENT, STRUCTURAL, &amp; OTHER DRAINS

		Dam <sup>1/</sup>		Other	
		left	right	( )	( )
Depth of Flow (in inches above invert)	With any obstruction	<u>1/4</u>	—	—	—
	Without any obstruction	—	<u>1/4</u>	—	—
Turbidity of Discharge (yes, no)	With any obstruction	<u>NR</u>	—	—	—
	Without any obstruction	—	<u>NR</u>	—	—
Condition of Protective Coating	Outside	<u>1</u>	<u>1</u>	—	—
	Inside	<u>1</u>	<u>1</u>	—	—
Obstruction in Flow (yes, no)		<u>YES</u>	<u>NR</u>	—	—
Animal Guard Condition		<u>1</u>	<u>1</u>	—	—
Outlet Condition		<u>1</u>	<u>1</u>	—	—
Retarding Pool Elevation (ft. msl) _____ or _____ (ft.) above _____ below _____					
Other _____					

COMMENTS SMALL AMOUNT OF ALGAE IN LT. PIPE

<sup>1/</sup>Looking downstream.

<sup>2/</sup>Including wave, surface, stream, manhole, and livestock erosion.

## PAVEMENT AND EXCAVATED SLOPES

(Report riprap and vegetation and erosion condition under Items 4 and 5.)

	Dam	Dike	Emergency Spillways		Other	
			left	right	( )	( )
Sliding or sloughing	<u>1</u>	—	<u>3</u>	—	—	—
Holes (rotent and other)	<u>1</u>	—	<u>1</u>	—	—	—
(check especially at embankments)						
Excessive settlement (embankments)	<u>1</u>	—	<u>1</u>	—	—	—
Cracks						
Traverse	<u>1</u>	—	<u>1</u>	—	—	—
Longitudinal	<u>1</u>	—	<u>1</u>	—	—	—
Seepage <u>1/</u>	<u>1</u>	—	<u>2</u>	—	—	—
Piping <u>2/</u>	<u>1</u>	—	<u>1</u>	—	—	—

COMMENTS SLIDING OR SLOWING HAS OCCURRED AT  
NUMEROUS LOCATIONS OF WHICH 7 ARE SIGNIFICANT.  
NINE OF THESE HAVE DEPOSITED MATERIAL IN THE  
RAIL GULLY OR DIRM. THE SEVENTH IS LOCATED  
BETWEEN THE DIRM AND THE SILLON FLOOR

## 277549

	Displ. of Rock	Loss of Spalls	Loss of Bedding	Erosion of Found.	Break- down of Rock
Dam					
Upstream berm	<u>1</u>	<u>1</u>	<u>1</u>	<u>1</u>	<u>1</u>
Principal Spillway Outlet	<u>1</u>	<u>1</u>	<u>1</u>	<u>1</u>	<u>1</u>
Embankment Gutters					
left <u>DWN STM</u>	<u>1</u>	<u>1</u>	<u>1</u>	<u>1</u>	<u>1</u>
right <u>UP STM</u>	<u>1</u>	<u>1</u>	<u>1</u>	<u>1</u>	<u>1</u>
Emergency Spillway					
location <u>DOWN CUT SLOPE</u>	<u>1</u>	<u>1</u>	<u>1</u>	<u>1</u>	<u>1</u>
location <u>DIPS AT SIDE</u>	<u>1</u>	<u>1</u>	<u>1</u>	<u>1</u>	<u>1</u>
Waterways					
location <u>EM. SP. AT SIDE</u>	<u>1</u>	<u>1</u>	<u>1</u>	<u>1</u>	<u>1</u>
location <u>                    </u>	<u>1</u>	<u>1</u>	<u>1</u>	<u>1</u>	<u>1</u>
Outlet Channel	<u>1</u>	<u>1</u>	<u>1</u>	<u>1</u>	<u>1</u>
Other <u>SEED</u>	<u>1</u>	<u>1</u>	<u>1</u>	<u>1</u>	<u>1</u>

COMMENTS IT APPEARS THAT THE BLANKS PAGE IS PARTIALLY  
FILLED W/ SAND GRAVEL & SMALL ROCK.  
WATER RESOURCES BOARD PERSONNEL WILL CHECK  
PIPPER ON CARD

/100% availability at downstream face of embankments.

# MAINTENANCE CHECKLIST FOR DAMS AND CONTROL STRUCTURES

This maintenance checklist is a guide for determining the maintenance required for Public Law 565 flood control structures in New Hampshire. It doesn't take the place of experience and judgment and is not inclusive. Items of a difficult nature to check, such as principal spillway conduit condition, are not included. Intensive checks of these items are necessary at proper intervals. Review of built drawings, the design folder, structure history, and previous maintenance reports should be part of the inspection. Prompt maintenance is a vital part of safe and effective operation.

Except where otherwise indicated, completion of this form may be facilitated by ranking maintenance items on a 1 to 4 basis where

- 1 = satisfactory
- 2 = satisfactory, but check carefully at next inspection
- 3 = requires maintenance this season
- 4 = requires immediate attention.

WATERBODY RALEIGH RIVER SITE 6A DATE 5-20-77  
 INSPECTED BY KERR GANNENY LAHALL  
MILLER NELSON MCDONALD

## 1. GENERAL ITEMS

Access Road.	.	.	.	.	.	.	.	.	.	2
Site Fencing.	.	.	.	.	.	.	.	.	.	1
Traffic Conditions.	.	.	.	.	.	.	.	.	.	1
Vandalism Control.	.	.	.	.	.	.	.	.	.	1
Trash Control.	.	.	.	.	.	.	.	.	.	3

COMMENTS SOME PUTTING OF ACCESS ROAD. TRASH  
ON DAM & IN L.S. TRASH PAIL SHOULD BE REMOVED

## 2. RESERVOIR

Timber stand at reservoir.	.	.	.	.	.	.	.	.	.	2
Debris and slash.	.	.	.	.	.	.	.	.	.	2
Sediment level in relation to low stage inlet	.	.	.	.	.	.	.	.	.	

COMMENTS THERE ARE SOME BLOW DOWN VICTIMS  
THESE SHOULD BE REMOVED.

PAST INSPECTION REPORTS

AVAILABLE ENGINEERING DATA

1. A set of drawings (33 sheets), dated August 1973, showing plans and details of the dam and appurtenant structures.
  2. Design Data: including layout, hydraulic design, geology and soils reports, structural design, quantities and specifications.
  3. Construction Data: including as-built plans, job diaries, surveying records, test drilling logs, compaction test results, concrete tests, and certificate of completion.
- All of the above are on file with the U.S.D.A. Soil Conservation Service, Federal Building, Durham, N.H. 03824.






SECTION A-A

EARTH		FILL		REQUIREMENTS	
TYPE	MATERIAL	REQUIRED WATER CONTENT	MAXIMUM DENSITY	DEFINITION	
NON-FRAGMENTARY LIKE	SILT, SAND AND GRAVEL	OPTIMUM TO +4% * OPTIMUM	95% MAXIMUM DENSITY BY ASTM D698 METHOD "A"		
	GRAVEL WITH SAND	WET		4 PASSES OF VIBRATORY ROLLER MIN. 12" WIDE WEIGHING MIN. 10 TON/FT WITH MIN IMPACT OF 22,200 LBS./MIN. 1200 TIMES/ MIN	

[illegible]

4 24" RE INFG CONC. PIPE

RECEIVED  
JAN 25




SECTION B-B


FIG 2 of 2

1 of 2

SECTION A-A



SECTION C-C



1 THE INFORMATION SHOWN ON THESE DRAWINGS IS BASED ON THE ORIGINAL CONSTRUCTION PLANS AND VISUAL OBSERVATIONS MADE DURING THE FIELD INSPECTION DIMENSIONS OR MATERIALS INDICATED ON THESE DRAWINGS WHICH WERE BELOW GRADE OR WATER DURING THE TIME OF INSPECTION WERE NOT VERIFIED

2 THE ELEVATIONS SHOWN ARE 1929 MSL DATUM

NATIONAL PROGRAM OF INSPECTION OF NON-FED DAMS	
SITE NO 6A	
BAKER FLOODWATER	
RESERVOIR	
LUHAI BROOK	WENTWORTH, N.H.

Figure 2 of 2

2 of 2

APPENDIX C

PHOTOGRAPHS

FOR LOCATION OF PHOTOS, SEE FIGURE 1  
LOCATED IN APPENDIX B



PHOTO NO. 1 - View of dam and portion of reservoir from left bank.



PHOTO NO. 2 - View of dam crest from right abutment.



PHOTO NO. 3 - View of reservoir from right abutment.



PHOTO NO. 4 - Reservoir from left side of reservoir, looking upstream. Note roadway and culvert.



PHOTO NO. 5 - View of upstream slope of dam from right abutment.



PHOTO NO. 6 - Upstream slope of dam and right abutment,  
from slope adjacent to principal spillway.




PHOTO NO. 7 - Downstream face of dam from emergency spillway dike.




PHOTO NO. 8 - View of downstream face of dam and portion of emergency spillway.




PHOTO NO. 9 - View of right side of riser and principal spillway.




PHOTO NO. 10 - View of left side of riser and principal spillway.






PHOTO NO. 11 - View of downstream side of riser and principal spillway.



PHOTO NO. 12 - View of principal spillway outlet pipe and discharge channel.



PHOTO NO. 13 - View of  
outlet pipe and plunge  
pool stilling basin.



PHOTO NO. 14 - View of discharge channel.




PHOTO NO. 15 - View of upstream portion of emergency spillway.



PHOTO NO. 16 - View of downstream portion of emergency spillway from axis of dam.



PHOTO NO. 17 - View of crest of emergency spillway from spillway channel.



PHOTO NO. 18 - View of emergency spillway outlet, downstream of crest, from dam.

APPENDIX D  
HYDROLOGIC AND HYDRAULIC COMPUTATIONS

INTB

WARD NEEDLES TAMMEN &amp; BERGENDOFF

Made by	SA	Date	11/17/77	Sheet #	1 of 1
Checked by	SA	Date	11/17/77	Sheet #	1 of 1

## HYDRAULIC & HYDROLOGY

Page 1 of 1 Dam # 6A is located on the Tual River  
in the Town of Wentworth, N.H. in the  
Merrimack River Basin.

Classification CIEB - Intermediate  
Hazard: High

Location SA. 115 mi.  
William Evans Mountainous - 222 ft  
Average Slope 4-5 percent

Reservoir: Reservoir is 75 ft. x 15 ft.  
Stream CIEB 115 ft  
Avg. Top Data E 975 ft  
Stream 115 ft  
Avg. Top Data 971.5 ft  
Stream 115 ft

Dam: 115 ft  
Height 730 ft  
Width 60 ft

Spillway  
Reservoir: 90-7 ft  
Avg. width: 10 ft  
Avg. depth: 10 ft  
Avg. width: 10 ft  
Avg. depth: 10 ft

See Appendix E for details

HYDROGRAPH COMPUTATION

WATERSHED OR PROJECT WATER STATE W. V.

STRUCTURE, SITE OR SUBAREA DATE 10/1/64

DR. AREA 2.15 SQ. MI.  $T_c$  0.8 HR. RUNOFF CONDITION NO. 12

RUNOFF CURVE NO. 2 STORM DISTRIB. CURVE 3 HYDROGRAPH FAMILY NO. 1

STORM DURATION 4 HR. RAINFALL: POINT 1.5 IN. AREAL 1.5 IN.

$Q$  1.5 IN. COMPUTED  $T_p$  1.2 HR.  $T_0$  0.8 HR.

$1T_0 + T_p$  COMPUTED 2.0 USED 4 REVISED  $T_p$  1.2

$q_p = \frac{4.84 A}{REV T_p} = \frac{4.84 \times 2.15}{1.2} = 8.67$  CFS.  $Q_{90} = 0.95 Q_p = 8.23$  CFS.

$q(COLUMN) = 1 T_p REV T_p$   $q(COLUMN) = (REV T_p) Q_{90}$

LINE NO.	t HOURS	q CFS	LINE NO.	t HOURS	q CFS	LINE NO.	t HOURS	q CFS
1	0	0	21	2.0	1.5	41		
2	0.2	0	22	2.2	7.1	42		
3	0.4	0	23	2.4	2.2	43		
4	0.6	0	24	2.6	8.5	44		
5	0.8	0	25	2.8	5.5	45		
6	1.0	0	26	3.0	1.2	46		
7	1.2	0	27	3.2	7	47		
8	1.4	0	28	3.4	0	48		
9	1.6	0	29	3.6		49		
10	1.8	0	30	3.8		50		
11	2.0	8.67	31	4.0		51		
12	2.2	7.1	32	4.2		52		
13	2.4	2.2	33	4.4		53		
14	2.6	8.5	34	4.6		54		
15	2.8	5.5	35	4.8		55		
16	3.0	1.2	36	5.0		56		
17	3.2	7	37	5.2		57		
18	3.4	0	38	5.4		58		
19	3.6		39	5.6		59		
20	3.8		40	5.8		60		

Reproduced from  
best available copy.

HYDROGRAPH COMPUTATION

WATERWORKS PROJECT \_\_\_\_\_ STATE Ill.

DRAINAGE AREA TO R.O. AREA \_\_\_\_\_

DR. AREA \_\_\_\_\_ SQ. MI.  $T_c$  \_\_\_\_\_ HR. RUNOFF CONDITION NO. \_\_\_\_\_

RUNOFF CURVE NO. \_\_\_\_\_ STORM DIST. CURVE \_\_\_\_\_ HYDROGRAPH FAMILY NO. \_\_\_\_\_

STORM DURATION \_\_\_\_\_ HR. RAINFALL \_\_\_\_\_ IN. AREAL \_\_\_\_\_ IN.

COMPUTED  $T_p$  \_\_\_\_\_ HR.  $T_o$  \_\_\_\_\_ HR.

$T_o + T_p$  \_\_\_\_\_ COMPLETED \_\_\_\_\_ USED \_\_\_\_\_ REVISED  $T_p$  \_\_\_\_\_

$Q_p = \frac{484A}{T_o + T_p} = \frac{484 \times 100}{1.5 + 1.5} = 15777$  CFS.  $Q_{3p} = \frac{1}{3} Q_p = 5259$  CFS.

1 COLUMN =  $T_p$  RE  $T_p$

4 COLUMNS =  $100/T_p$  21p

LINE NO.	t HOURS	q CFS	LINE NO.	t HOURS	q CFS	LINE NO.	t HOURS	q CFS
1			21			41		
2			22			42		
3			23			43		
4			24			44		
5			25			45		
6			26			46		
7			27			47		
8			28			48		
9			29			49		
10			30			50		
11			31			51		
12			32			52		
13			33			53		
14			34			54		
15			35			55		
16			36			56		
17			37			57		
18			38			58		
19			39			59		
20			40			60		

Reproduced from  
best available copy.



PC 6 A7V PFC 15

314: E

—

—

100

22

10


10

1  
 2  
 3  
 4  
 5  
 6  
 7  
 8  
 9  
 10  
 11  
 12  
 13  
 14  
 15  
 16  
 17  
 18  
 19  
 20  
 21  
 22  
 23  
 24  
 25  
 26  
 27  
 28  
 29  
 30  
 31  
 32  
 33  
 34  
 35  
 36  
 37  
 38  
 39  
 40  
 41  
 42  
 43  
 44  
 45  
 46  
 47  
 48  
 49  
 50  
 51  
 52  
 53  
 54  
 55  
 56  
 57  
 58  
 59  
 60  
 61  
 62  
 63  
 64  
 65  
 66  
 67  
 68  
 69  
 70  
 71  
 72  
 73  
 74  
 75  
 76  
 77  
 78  
 79  
 80  
 81  
 82  
 83  
 84  
 85  
 86  
 87  
 88  
 89  
 90  
 91  
 92  
 93  
 94  
 95  
 96  
 97  
 98  
 99  
 100  
 101  
 102  
 103  
 104  
 105  
 106  
 107  
 108  
 109  
 110  
 111  
 112  
 113  
 114  
 115  
 116  
 117  
 118  
 119  
 120  
 121  
 122  
 123  
 124  
 125  
 126  
 127  
 128  
 129  
 130  
 131  
 132  
 133  
 134  
 135  
 136  
 137  
 138  
 139  
 140  
 141  
 142  
 143  
 144  
 145  
 146  
 147  
 148  
 149  
 150  
 151  
 152  
 153  
 154  
 155  
 156  
 157  
 158  
 159  
 160  
 161  
 162  
 163  
 164  
 165  
 166  
 167  
 168  
 169  
 170  
 171  
 172  
 173  
 174  
 175  
 176  
 177  
 178  
 179  
 180  
 181  
 182  
 183  
 184  
 185  
 186  
 187  
 188  
 189  
 190  
 191  
 192  
 193  
 194  
 195  
 196  
 197  
 198  
 199  
 200  
 201  
 202  
 203  
 204  
 205  
 206  
 207  
 208  
 209  
 210  
 211  
 212  
 213  
 214  
 215  
 216  
 217  
 218  
 219  
 220  
 221  
 222  
 223  
 224  
 225  
 226  
 227  
 228  
 229  
 230  
 231  
 232  
 233  
 234  
 235  
 236  
 237  
 238  
 239  
 240  
 241  
 242  
 243  
 244  
 245  
 246  
 247  
 248  
 249  
 250  
 251  
 252  
 253  
 254  
 255  
 256  
 257  
 258  
 259  
 260  
 261  
 262  
 263  
 264  
 265  
 266  
 267  
 268  
 269  
 270  
 271  
 272  
 273  
 274  
 275  
 276  
 277  
 278  
 279  
 280  
 281  
 282  
 283  
 284  
 285  
 286  
 287  
 288  
 289  
 290  
 291  
 292  
 293  
 294  
 295  
 296  
 297  
 298  
 299  
 300  
 301  
 302  
 303  
 304  
 305  
 306  
 307  
 308  
 309  
 310  
 311  
 312  
 313  
 314  
 315  
 316  
 317  
 318  
 319  
 320  
 321  
 322  
 323  
 324  
 325  
 326  
 327  
 328  
 329  
 330  
 331  
 332  
 333  
 334  
 335  
 336  
 337  
 338  
 339  
 340  
 341  
 342  
 343  
 344  
 345  
 346  
 347  
 348  
 349  
 350  
 351  
 352  
 353  
 354  
 355  
 356  
 357  
 358  
 359  
 360  
 361  
 362  
 363  
 364  
 365  
 366  
 367  
 368  
 369  
 370  
 371  
 372  
 373  
 374  
 375  
 376  
 377  
 378  
 379  
 380  
 381  
 382  
 383  
 384  
 385  
 386  
 387  
 388  
 389  
 390  
 391  
 392  
 393  
 394  
 395  
 396  
 397  
 398  
 399  
 400  
 401  
 402  
 403  
 404  
 405  
 406  
 407  
 408  
 409  
 410  
 411  
 412  
 413  
 414  
 415  
 416  
 417  
 418  
 419  
 420  
 421  
 422  
 423  
 424  
 425  
 426  
 427  
 428  
 429  
 430  
 431  
 432  
 433  
 434  
 435  
 436  
 437  
 438  
 439  
 440  
 441  
 442  
 443  
 444  
 445  
 446  
 447  
 448  
 449  
 450  
 451  
 452  
 453  
 454  
 455  
 456  
 457  
 458  
 459  
 460  
 461  
 462  
 463  
 464  
 465  
 466  
 467  
 468  
 469  
 470  
 471  
 472  
 473  
 474  
 475  
 476  
 477  
 478  
 479  
 480  
 481  
 482  
 483  
 484  
 485  
 486  
 487  
 488  
 489  
 490  
 491  
 492  
 493  
 494  
 495  
 496  
 497  
 498  
 499  
 500  
 501  
 502  
 503  
 504  
 505  
 506  
 507  
 508  
 509  
 510  
 511  
 512  
 513  
 514  
 515  
 516  
 517  
 518  
 519  
 520  
 521  
 522  
 523  
 524  
 525

1

100

[illegible]



TIME

TEMPERATURE

100°C

<b>HINTS</b> HOWARD NEEDLES TAMMEN & BERGENDOFF For <u>3122-2H</u>	Made by <u>KY</u>	Date <u>5/29/79</u>	Job # <u>5763-11-06</u>
	Checked by <u>1.19</u>	Date <u>6/15/79</u>	Sheet # <u>7</u>

Step 4 Reach Outflow  $C = 1209 \text{ mm ft}$

$$Q_{R1} = 112,200 \text{ cfs}$$

$$Stage_1 = 28.6$$

$$area_1 = 3475 \text{ ft}^2$$

$$V_1 = \frac{3475 \times 7200}{43560} = 574 \text{ mm ft} < \frac{1209}{2}$$

Reach length OK

$$Q_{R2} = 112,200 \left(1 - \frac{574}{1209}\right) = 52,900 \text{ cfs}$$

$$Stage_2 = 22.3 \text{ ft}$$

$$area_2 = 2029 \text{ ft}^2$$

$$V_2 = \frac{2029 \times 7200}{43560} = 335 \text{ mm ft}$$

$$V_{ave} = 455 \text{ mm ft}$$

$$Q_{R3} = 112,200 \left(1 - \frac{455}{1209}\right) = 70,000 \text{ cfs}$$

$$V_{ave} = 23 \text{ ft}$$

<b>UNITED</b> HOWARD NEEDLES TAMMEN & BERGENDOFF For <u>                    </u>	Made by <u>RY</u>	Date <u>5/29/77</u>	Job No. <u>5925-11-06</u>
	Checked by <u>WV</u>	Date / <u>11/10/77</u>	Sheet No. <u>6</u>

## Estimate of Downstream Damage

### Step 1 Reservoir Storage

Top of Dam @ elev 975.1  
 Storage 1209 acre-ft

### Step 2 In-Reach Situation

Remain: 9/27/77 @ 7<sup>th</sup>

100% of dam length = 750 ft

100% of dam length = 750 ft  
 100% of dam length = 750 ft  
 100% of dam length = 750 ft

100% of dam length = 750 ft

100% of dam length = 750 ft

100% of dam length = 750 ft


### Step 3 Flood Damage

100% of dam length = 750 ft

100% of dam length = 750 ft


100% of dam length = 750 ft

100% of dam length = 750 ft




<u>Estimated Damages</u>	
100%	2000
75%	1600
50%	1200
25%	800
10%	400
5%	200
1%	100

RECEIVED - FEBRUARY 1964



11-11-64







**HNTB**

HOWARD NEEDLES TAMMEN &amp; BERGENDOFF

For

Made by

Checked by

Date

Date

Sheet

Sheet No

5

STAINLESS STEEL PIPE - 12" O.D. - 1/2" WALL THICKNESS

$$Q_1 = 4000 \text{ lb}$$

$$r_{unroof} = 9.5 \text{ inches}$$

$$Q_2 = Q_1 \left(1 - \frac{32}{9.5}\right)$$

The above is the value from Figure 3, minus 32% of the

$$Q_2 = \frac{4000 \text{ lb} \times (1 - \frac{32}{9.5})}{335 \text{ lb/m} \times 640 \text{ ft}} = 1.1 \text{ lb/m} \times 640 \text{ ft}$$

Q <sub>1</sub>	Q <sub>2</sub>	Q <sub>3</sub>	Q <sub>4</sub>
4000	769	431	2195
3000	120	403	2052
2000	783	474	1925
1000	734	523	1800

The above is the value from Figure 3, minus 32% of the

From Figure 3  $Q_2 = 1.1 \text{ lb/m} \times 640 \text{ ft}$ 

$$Q_2 = 1.1 \text{ lb/m} \times 640 \text{ ft}$$

The above is the value from Figure 3, minus 32% of the

**HNTB**

HOWARD NEEDLES TAMMEN &amp; BERGENCOFF

Made by

RY

Date

7/12/79

Job No.

SD-15-11-26

Checked by

IY

Date

7/15/79

Sheet No.

1

For

Lake-6A

Step 3 Estimate of Surge Effect

$$QR = 1000 \text{ cfs}$$

$$\text{Runoff} = 19 \text{ inches}$$

$$QR_2 = QR \left(1 - \frac{2.72}{19}\right)$$

Run wave read from figure 1 minus 2.5 wave

$$\text{tor}(in) = \frac{\text{tor wave-ft} \times 2 \text{ in/ft}}{3.35 \text{ wave} \times 640 \text{ wave/ft}^2} = .0056 (3.5)$$

Dist	tor(wave-ft)	tor(in)	QR cfs
173	569	4.31	4185
174	726	4.63	3050
175	773	4.94	5920
176	934	5.23	5220
177	717	5.54	5670

See figure 2 for Plot and Final outflow

From Figure 2 Outflow 5760 cfs

Stage 976.5 cfs

1.2 mrdm

**HNTB**

Made by

EY

Date

11/1/79

Sheet

255-1-26

HOWARD NEEDLES TAMMEN &amp; BERGENDOFF

Checked by

VIV

Date

11/1/79

Sheet

3

For E. J. L. A.

STAGE Calculation of Test Flood SurchargeStage - Discharge Curve

<u>Elev</u>	<u>Test stage</u> <u>Channel Section</u>	<u>A Riser -</u> <u>Rip-Flow</u>	<u>B Emergence</u> <u>Surcharge</u>	<u>C Crest of</u> <u>Dam</u>	<u>Total</u>
771	0	227 cfs	-	-	227 cfs
772	1	231	133 cfs	-	364
773	2	233	470	-	703
774	3	235	730	-	965
775	4	237	1515	-	1752
776	5	237	2325	1925	4487
777	6	241	3150	5380	8571
778	7	242	4125	11722	16089
779	8	237	7603	-	7840

A. from Flood Routing Data SA Dam Look at 11/1/79 H.H.

B. from H.H.

C. from H.H. Discharge Data at 11/1/79

$$Q = 244 \text{ cfs}$$

$$L = 309$$

$$L = 730$$

$$Q = 2236 \text{ cfs}$$

<b>HNTB</b> HOWARD NEEDLES TAMMEN & BERGENDOFF For <u>Size #6A</u>	Made By <u>RY</u>	Date <u>5/11/73</u>	Drawn By <u>3955-11-23</u>
	Checked By <u>W.H.C.</u>	Date <u>5/15/73</u>	Drawn By <u>2</u>

## STEP #1 Calculation of Test Flood Inflow

Classification: Size: Intermediate  
Hazard: High

Hydrologic Evaluation & Flashflood - Recommend  
use of full PMF

There is no range of values for this classification

Use Mountaineers curve as design slope is  
approximately 400 ft/mi.

$$PMF = 2380 \text{ cpm}$$

$$\text{Test Flood Inflow} = 2380 \times 3.35 \text{ mi}^2 = 7980 \text{ gpm}$$

As this is a flood control reservoir the portion  
of the storage volume above the recreation pool  
can be used to store PMF runoff.

Reproduced from  
best available copy.

STATE OF TEXAS  
COUNTY OF DALLAS

BEFORE ME, the undersigned authority, on this day personally appeared \_\_\_\_\_, known to me to be the person whose name is subscribed to the foregoing instrument, and acknowledged to me that he executed the same for the purposes and consideration therein expressed.

DEPARTMENT OF AGRICULTURE  
COUNTY OF DALLAS

Given under my hand and seal of office this \_\_\_\_\_ day of \_\_\_\_\_, 19\_\_\_\_.

Notary Public for the State of Texas

My commission expires \_\_\_\_\_  
at \_\_\_\_\_  
Dallas, Texas

Notary Public for the State of Texas

My commission expires \_\_\_\_\_  
at \_\_\_\_\_  
Dallas, Texas

Notary Public for the State of Texas

My commission expires \_\_\_\_\_  
at \_\_\_\_\_  
Dallas, Texas


Notary Public for the State of Texas


My commission expires \_\_\_\_\_  
at \_\_\_\_\_  
Dallas, Texas

Reproduced from  
best available copy.

U S ( P A T I E N T ) A C T I V E









APPENDIX E

INFORMATION AS CONTAINED IN  
THE NATIONAL INVENTORY OF DAMS

77-17-17  
HAWAII

# INVENTORY OF DAMS IN THE UNITED STATES

STATE OF HAWAII	COUNTY OF HAWAII	COUNTY OF HAWAII	NAME	LATITUDE (NORTH)	LONGITUDE (WEST)	REPORT DATE
STATE OF HAWAII	COUNTY OF HAWAII	COUNTY OF HAWAII	BAKER FLOOD-ATM RESERVOIR SITE 6A	4351.3	7155.6	22JUN79

POPULAR NAME	NAME OF IMPOUNDMENT
GRUVER C BRECK DAM	

REGION/RIVER OR STREAM	NEAREST DOWNSTREAM CITY-TOWN-VILLAGE	DIST FROM DAM (MI)	POPULATION
01 08 TUNAL BROOK	WEST HUNNEY	5	

TYPE OF DAM	YEAR COMPLETED	PURPOSES	STORAGE CAPACITY		IMPOUNDING CAPACITIES		DIST O-W-N	FED R	PRV/FED	SCS A	VER/DATE
			STORAGE HEIGHT (FT)	STORAGE VOLUME (CUY)	MAXIMUM (ACR)	NORMAL (ACR)					
REGG	1975	C4	65	60	1209	526					

REMARKS

D/S HAS	SPILLWAY TYPE	MAXIMUM DISCHARGE (CUY)	VOLUME OF DAM (CUY)	POWER CAPACITY INSTALLED (KW)	POWER CAPACITY PROPOSED (KW)	NAVIGATION LOCKS	
						LENGTH (FT)	WIDTH (FT)
2	750 U	80	1663	120943			

OWNER	ENGINEERING BY	CONSTRUCTION BY
N H WATER RESOURCES HD	SOIL CONSERVATION SER	ROBIE CONSTRUCTION COINC

REGULATORY AGENCY	
DESIGN	OPERATION
NONE	NONE

INSPECTION BY	INSPECTION DATE	AUTHORITY FOR INSPECTION
HOWARD NEEDLES TAMMEN BERGENDOFF	17MAY79	PUBLIC LAW 92-367

REMARKS

**END**

**FILMED**

**9-85**

**DTIC**